



Port 1 ST Fiber Connections
on Underside of Board
TX Connection RX Connection

Port 5 ST Fiber Connections
on Underside of Board
TX Connection RX Connection

P/N
11054-002 Rev. B



BUILD NO.